



SOLID Rack assembly instruction




Part list



2x




44x




50x



4x




1x




2x




2x



1



2



3